

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors

: S. C. YOON et al.

Certificate of Corrections Branch

Patent No.

: 6,925,360

Issued: August 2, 2005

Appl. No.

: 10/701,501

Filed: November 6, 2003

For

: AIR CONDITIONER CONTROL SYSTEM USING A TELEPHONE

NETWORK AND METHOD FOR OPERATING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner For Patents U.S. Patent and Trademark Office Customer Service Window Randolph Building 401 Dulany Street Alexandria, VA 22314

Certificate

FEB 0 9 2006

of Correction

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent, which is the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction. Since the error is the fault of the U.S. Patent and Trademark Office, no fee is due.

On the cover of the printed patent, at Item (57), Abstract, line 8, "there" should be ---the---. This appeared correctly on page 16, line 7 of the Specification filed November 6, 2003.

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:

P23893.A20

On the cover of the printed patent, at Item (57), Abstract, line 8, "there" should be ---the---. Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted, S. C. YOON et al.

Bruce H. Bernstein

Reg. No. 29,027

Steven Wegman Reg. No. 31,438

February 3, 2006 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION		
	Page <u>1</u> of <u>1</u>	
PATENT NO. : 6,925,360		
APPLICATION NO.: 10/701,501		
ISSUE DATE : August 2, 2005		
INVENTOR(S) : S. C. YOON et al.		
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:		
On the cover of the printed patent, at Item (57), Abstract, line 8, "there" should bethe		

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place

Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

	Dana 1 of 1	
PATENT NO. : 6,925,360	Page 1 of 1	
APPLICATION NO.: 10/701,501		
ISSUE DATE : August 2, 2005		
INVENTOR(S) : S. C. YOON et al.		
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:		
On the cover of the printed patent, at Item (57), Abstract, line 8, "there" should bethe	e	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

FEB 9 2006